# **CERN - European Organization for Nuclear Research**

LCD-Note-2009-000

# First radiation hardness results of the TeraPixel Active Calorimeter (TPAC) sensor

T. Price\*, N.K. Watson\*, Others<sup>†</sup>

\* University of Birmingham, <sup>†</sup> to be added

August 24, 2012

#### Abstract

The TeraPixel Active Calorimeter (TPAC) sensor is a Monolithic Active Pixel Sensors (MAPS) device that was developed for use as the active layers of a large area, digital electromagnetic calorimeter at a future  $e^+e^-$  collider. Although the radiation environment is expected to be relatively benign for such a machine, it is essential to characterise the behaviour of the sensor for this and other applications. This note presents the first studies of radiation hardness testing of the TPAC sensor up to integrated doses of 5 Mrad. Under realistic operating conditions a maximum decrease in the S/N of 8 % at 200 krad is observed.

August 24, 2012 – 12:01

## **1** Introduction

The detection of minimum ionising particles (MIPs) has been successfully demonstrated using CMOS Monolithic Active Pixel Sensors (MAPS) [1]. This technology allows the development of low noise, high sensitivity, radiation tolerant sensors. The cost per unit area of standard CMOS sensors is expected to be considerably lower than other technologies making it possible to build a whole ECAL with silicon readout. Sensor fabrication would be more straightforward with integrated electronics and a much wider choice of vendors leading to increased production speed and capacity. The CALICE-UK Collaboration [2] developed the TeraPixel Active Calorimeter (TPAC) Sensor for use in a binary readout (Digital) Electromagnetic Calorimeter (DECAL) within the detectors at a future  $e^+e^-$  collider such as the International Linear Collider (ILC). TPAC is the first prototype device for such an application. To date, no effort has been made to minimize the power consumtion of the sensors, a characteristic which will be essential in a DECAL. The readout is based on ILC bunch structures (5Hz bunch trains, each consisting of ~3000 bunches separated by a few hundred ns) but the timings could be optimized for alternative machines e.g the Compact Linear Collider (CLIC).

The TPAC sensor was primarily designed to be used in the low radiation environment of an ECAL at the ILC and as such, creating a radiation hard sensor was not one of the key design features. However, as possible uses for the TPAC sensors and the INMAPS technology [3] have broadened, such as vertexing [4] and tracking systems, and the higher radiation environment of the ECAL at CLIC, the sensors' response to radiation has been studied to characterize their performance.

Section 2 gives a brief overview of the TPAC sensor to be tested and the innovative INMAPS process which enables the use of CMOS sensors for efficient MIP detection. Section 3 outlines the methods used to characterise the pixels, allowing a quantitative evaluation of the impact of the irradiations. Finally, the results of the irradiations are presented in Section 4 with particular emphasis on the noise and pedestal shifts, and the impact on the signal to noise ratio, and conclusions are given in Section 5.

# 2 Pixel technology

### 2.1 TPAC Sensor

The TPAC sensor is the first sensor fabricated that utilises INMAPS technology (see Section 2.2) and the benefits to charge collection and pixel efficiency have been successfully demonstrated [5][6]. Due to the shower densities expected within the core of electromagnetic showers in a DECAL at a linear collider a pixel size of  $50 \times 50 \ \mu m^2$  was chosen for prototyping. This is required to ensure single pixel occupancy in events with a peak density of 100 particles/mm<sup>2</sup>. The detector geometry thus leads to  $\sim 10^{12}$  pixels in a complete DECAL system and the integrated readout electronics of the TPAC sensor are essential to minimise the deadspace associated with each pixel.

The prototype sensor contains 28224 pixels in a  $168 \times 168$  grid and is segmented in to four regions with each region served by a column of logic and SRAM for readout purposes (lighter, vertical areas in Figure 1). Each region of the sensor is subdivided into 168 rows of 42 pixels



Figure 1: Photograph of a bonded TPAC sensor showing the four vertical regions and the columns of logic and SRAM (lighter regions) which serve them.

with each row further divided into seven segments of six pixels [7]. Each pixel has four signal diodes and a hit is registered when the combined signal in a pixel goes above a given threshold (set in arbitrary units of DAQ Threshold Units (DTU)). The location and time stamp of the hit is stored and the complete sensor is read out at the end of each bunch train. Due to the size of the in-sensor memory, each segment can have a maximum of 19 hits in each bunch train before saturation occurs and it is thus essential to keep noise to a minimum to avoid losing genuine hits due to the memory filling.

# 2.2 INMAPS Process

In a standard CMOS sensor, the charge diffuses to the signal diodes where it is collected. However, during diffusion, the charge is also collected parasitically at other N-wells, reducing the collection efficiency. This causes a significant depreciation in the sensor performance and prohibits the use of PMOS components. The INMAPS process has been develped [3] specifically to allow the N-wells in the PMOS to be shielded using a deep P-well implant, as shown in Figure 2. This deep P-well shields the parasitic N-wells of the PMOS components and as such decreases the parasitic charge collection. This allows full CMOS technology to be used whilst preventing the degradation to the sensor performance. The INMAPS process also allows sensors to be fabricated with a high-resitivity substrate. There are four variants to the TPAC sensor:

- 12  $\mu$ m standard epitaxial layer
- 12  $\mu$ m standard epitaxial layer with INMAPS (refered to as "standard" in this note)
- 12  $\mu$ m high-resistivity epitaxial layer with INMAPS
- 18  $\mu$ m high-resistivity epitaxial layer with INMAPS



Figure 2: Schematic of a typical standard CMOS sensor demonstrating the charge diffusion to the diodes (left), and a CMOS sensor utilising INMAPS where the charge is repelled from the deep P-well (right).

# 3 Sensor characterisation

Each pixel is characterised by its pedestal and noise level. Both of these are found by performing a threshold scan on each pixel and looking at the number of hits as a function of the threshold. The threshold scans were conducted in a darkened box to ensure that there was no interference from photons causing genuine hits in the sensors. The results of such a scan for a typical pixel are shown in Figure 3 where the mean value is the pedestal of the pixel and the width is the associated noise. Carrying out scans for all pixels in a sensor gives two corresponding spectra for each device (Figure 4) which can be compared after each dose to investigate the changes to the sensor. The pedestal spectra were fitted with a simple Gaussian and the mean value extracted along with the corresponding error. The noise spectra however were fitted with a Gaussian convoluted with a Landau distribution with the noise corresponding to the fit maxima.

During normal operation the sensors are trimmed so that all the pedestals line up around 100 DTU. However, during the radiation tests the sensors were used untrimmed because the trimming process takes 60 hours per sensor and the *changes* in the noise and pedestal, rather than their absolute values, were the characteristics of interest. The relative changes to the noise were calculated using:

$$f\Delta = \frac{X_{\text{Dose}} - X_{0\text{krad}}}{X_{0\text{krad}}} \quad , \tag{1}$$

and the pedestal shift was calculated using:

$$\Delta = X_{\text{Dose}} - X_{0\text{krad}} \quad , \tag{2}$$

where  $X_{Dose}$  and  $X_{0krad}$  are the pedestal/noise value for a specific dose and zero dose respectively. The relative changes to the pedestal were not calculated as the pedestal of an untrimmed sensor is approximately zero leading to large relative values.



Figure 3: The results of a typical threshold scan on a single pixel where the mean is the pedestal and the width of the gaussian is the noise in the pixel

# 4 Irradiation studies

Eight sensors have been irradiated with 50 keV x-rays, under two different bias, 0V and 1.8V (ground and operating voltages) up to doses of 5000 krad and 200 krad respectively, as summarised in Table 1. Also studied were the effects of dose rate with the sensors exposed at 60 rad/s and 6 rad/s, and the effect of using a high resistivity epitaxial layer. The sensors held at ground were exposed in various dose steps of between 200 krad and 1000 krad, while the sensors held at 1.8V were exposed in steps of 20 krad. After each dose the pixels were characterised to quantify the effect on the pixels. The x-ray source delivered an exposure to all pixels that was uniform to within approximately 10 % leading to an estimate of the error on the delivered dose of 0.1 times the delivered dose.

The x-rays will liberate electrons in the silicon with a maximum energy of 50 keV which in turn will impart a maximum of 0.19 eV upon a recoiled silicon atom. In silicon the displacement damage threshold is 21 eV [8] and as such the damage to the sensors cannot be from bulk damage and must be surface effects such as charge trapping at boundary interfaces.

Between irradiations the sensors were kept in a freezer at  $-20^{\circ}$ C to limit the amount of annealing. As a threshold scan on all the pixels in the sensor took approximately 6 hours only a quarter of the sensor was scanned following each irradiation. This was essential as the annealing in the sensor would have been accelerated as the operating temperature of the sensors is greater than room temperature and this could have caused discrepancies in the results.



Figure 4: Example of the pedestal and noise spectra formed from scanning all 28224 pixels in a sensor with the fits overlayed

### 4.1 Noise and Pedestals - bulk pixels

#### 4.1.1 Unpowered sensors

Four standard sensors were held at ground during the exposure with two receiving integrated doses of 1000 krad and the others receiving 5000 krad, all at a dose rate of 60 rad/s. These studies were performed to allow a comparison between the effects of bias in the sensors during exposure (Section 4.1.2).

At 1000 krad the noise increased in all sensors between 5 % and 8 %. Pairs of sensors 3 and 6, and sensors 1 and 4 were in good agreement within each pairing. At 5000 krad the noise in sensor 3 had increased by 18 % and sensor 6 by 21 % (Figure 5).

Over the same range of doses the pedestals also increased but by between 1.3 DTU (10 %) and 3.7 DTU (25 %) at 1000 krad rising to a maximum increase of 3.9 DTU (35 %) at 5000 krad. As the changes in the noise and pedestals were different this suggests that there could be multiple sources of damage to the sensors caused by the radiation.

#### 4.1.2 Powered sensors

Four additional sensors were exposed to radiation whilst held at their operating voltage of 1.8 V. Two of these were standard sensors, and the third was a high resistivity 18  $\mu$ m sensor; all three were irradiated at a dose rate of 60 rad/s. The fourth sensor was a standard sensor with a dose rate of 6 rad/s in order to test whether the results were rate dependent. Due to problems with loading configuration data on to the sensors (see Section 4.1.2) the powered sensors were only



Figure 5: The fractional changes in noise (left) and absolute changes in pedestal (right) from zero dose for the four sensors held at ground during exposure

exposed to small integrated doses of between 200 krad and 240 krad in stages of 20 krad.

Figure 6 shows that the noise once again increases with dose as expected with a maximum increase in sensor 9 of 9 %. The noise changes in the powered sensors at 200 krad (4% to 8 %) coincide with the noise changes in the unpowered sensors at 1000 krad (5 % to 8 %) implying that bias in the sensors accelerates the increase in the noise (see Table 1). The noise in sensor 10 was observed to fall slightly. Although this sensor was exposed at the low dose rate it is believed that the decrease is more likely to be an artifact of the fit used to extract the noise.

The behaviour of the pedestal when the sensors were powered during irradiation was found to be very different to those that were held at ground. When powered the pedestal actually decreases with dose in all of the sensors up to  $\sim 200$  krad. A lower pedestal during sensor operation will lead to an increase in the noise rate of the sensors and as such this could be a very important feature at higher doses. The dose rate does not affect the pedestal shifts as the change in sensor 10 is in good agreement with the other sensors.

In the high resistivity epitaxial layer (sensor 12) the fractional changes in the noise are in agreement with the standard sensors. The pedestal actually decreases more than the standard sensors. This once again implies that there could be multiple sources for the damage to the sensor, an epitaxial layer independant source (noise) and an epitaxial layer dependant source (pedestal).

The pedestal changes actually decreased at the higher doses because problems with the shift register meant that the sensors underwent annealing whilst waiting for the sensors to be scanned. This set the limit on the maximum dose for which reliable characterisation of the sensors could be performed, as described below.

[pi	5000	.002 -	.457 -	$0.002  0.176 \pm 0.002$	$.450   3.872 \pm 0.463$	.002 -	.421 -	$0.003  0.213 \pm 0.003$	$).586   1.839 \pm 0.590$	1	1	1	ı	•	1	1	1
Dose [kra	1000	$0.055\pm0$	$3.661 \pm 0$	$0.080\pm 0$	$2.779\pm0$	$0.068\pm 0$	$2.425\pm0$	$0.083\pm 0$	$1.289\pm 0$	1	I		I	1	I	1	ı
	200	ı	I	1	I	$0.025\pm0.002$	$1.729\pm0.404$	$0.037\pm0.002$	$0.621\pm0.554$	$0.040\pm0.003$	$-14.585 \pm 0.556$	$0.088\pm0.003$	$-16.573 \pm 0.459$	$-0.030 \pm 0.004$	$-17.894 \pm 0.815$	$0.068\pm0.004$	$-21.596 \pm 0.881$
Darameter		Noise	Pedestal	Noise	Pedestal	Noise	Pedestal	Noise	Pedestal	Noise	Pedestal	Noise	Pedestal	Noise	Pedestal	Noise	Pedestal
Dose Pate [rad/c]	TUP THE FIGURE	60	00	70	00	60	00	٤0	00	60		60		Q		60	
ıl Layer	Type	معملمعط	stanuaru	-tondond	Stanuaru	معملمهما	Stailualu	aton dond	Stallualu	معملمهما	Stallualu	معملمهما	Stallualu	معملمعط	Stallualu	hich societivity	
Epitaxis	Thickness $[\mu m]$	5	17	2	17	5	17	5	71	2	17	5	17	5	71	0	10
Sancor	TOSTIC	•	-	,	n	-	4	4	D	ç	4	c	ע	01	10	5	17

Table 1: Table of the fractional changes in the noise and pedestals shifts from zero dose to various doses. Sensors 1, 3, 4, and 6 were unpowered during irradiation; sensors 2, 9, 10, and 12 were powered; sensor 10 had a lower dose rate of 6 rad/s; and sensor 12 had an 18  $\mu$ m high-resitivity epitaxial layer.

### August 24, 2012 – 12:01



Figure 6: The fractional changes in noise (left) and and absolute changes in pedestal (right) from zero dose for the four sensors held at operating voltage. Sensor 10 was exposed at the lower rate of 6 rad/s and sensor 12 was the 18  $\mu$ m high resistivity epitaxial layer.

**Shift Register Problems** The configuration data is loaded on to the pixels by a "three-phase clock" shift register and this data contains the trim values of each pixel as well as the pixel masks, which can be used to define a set of pixels to be excluded from the readout. In the TPAC sensor if more than a few hundred pixels fire at the same time the pixels suffer from noise pick-up [6]. To work around this problem, during a threshold scan only one column of 168 pixels was unmasked at a given time. At the higher doses the values read in to and subsequently returned from the shift register were different in some pixels. Due to the nature of the shift register structure, a single bad register in a column of pixels can corrupt the whole column. This leads to the possibility of the mask values in an entire column being invalid and unmasking an additional 168 pixels during the scan. If there are too many bad columns it can prevent the sensor being reliably read out until the shift register is repaired. There are two potential ways of repairing the shift register; adjusting the voltage that drives the shift register; or allowing the sensor to anneal.

Figure 7 shows the number of bad columns in the shift register for various shift register supply voltages at doses of 0, 100, 200, and 220 krad for Sensor 2. This sensor had one bad column in the shift register before exposure so it was essential not to develop any more. It is clear that at 100 krad there is a large range of voltages over which just one bad column is present in the register, so the sensor functions correctly. At 200 krad this behaviour has changed so that there is no voltage at which the register has just one bad column and with a further increase in dose up to 220 krad the number of bad columns has significantly increased. At these higher doses, adjusting the supply voltage does not solve the issue and as such the register must be allowed to anneal.





Figure 7: The number of bad columns in the shift register as a function of supply voltage for various doses of a standard 12  $\mu$ m sensor.



Figure 8: The number of bad columns vs anneal time for two different doses (left) and the total anneal time before the sensor could be reliably scanned vs dose for the same sensor (right).



Figure 9: The number of bad columns vs dose for the two standard sensors exposed at a rate of 60 rad/s and the standard sensor at 6 rad/s (sensor 10).

With the shift register supply voltage fixed at the design voltage of 1.65 V, the behaviour was studied in 30 minute intervals until the number of bad columns was sufficiently small that the sensor could be reliably read out. Figure 8 reiterates the increased number of bad columns with a higher dose and shows the progression of the recovery of the shift register. The time to recover increased from 300 minutes to 1400 minutes for 200 and 220 krad respectively. Because these large waiting times allow the damage to the sensor to anneal away, it was not possible to carry out measurements at the larger doses.

When the dose rate was reduced by a factor of 10, the shift register problems were vastly reduced. At 200 krad there were just three bad columns in the sensor exposed at the reduced rate compared to greater than 20 for the other two standard sensors (see Figure 9). This suggests that the shift register is annealing during exposure. When the sensors are held at ground during exposure the shift register behaves as expected up to very high doses so the bias in the sensor is impeding the recombination of the electron-hole pairs created by the radiation. As the pedestal shift in the low dose rate sensor is equivalent to the shift in the other sensors this implies that the damage to the shift registers is rate dependent and the damage causing the pedestal changes is rate independent. Due to this, in the low radiation level environments of a calorimeter system the sensor should be able to withstand integrated doses higher than those tested as the dose rate will be significantly lower.



Figure 10: An example of the oscilloscope trace of an Fe-55 event with fit overlayed (left), and the resulting spectrum created using the minima of each event (right).

### 4.2 Signal - analogue test pixels

The sensors were designed with two "test" pixels having analogue readout to complement the digital pixels and to allow the shape and the characteristics of the signal in the pixels to be studied. An Fe-55 source was placed adjacent to the test pixels, a threshold of 140 mV was set and any signal in the pixels greater than this threshold had the signal shape measured and recorded using an oscilloscope. The minima of the signal was found by fitting a second order polynomial and an energy spectrum was built up for the pixels' response (see Figure 10).

Fe-55 produces gamma radiation with two characteristic photons,  $k_{\alpha}$  and  $k_{\beta}$ , having energies of 5.9 keV and 6.5 keV respectively. The  $k_{\alpha}$  peak is the dominant decay with the  $k_{\beta}$  having a reduced rate. When the photons deposit energy in 12  $\mu$ m silicon they will liberate 1620 e<sup>-</sup> and 1778 e<sup>-</sup> respectively. When one of the photons from the decay interacts directly with one of the diodes in the sensor all of the energy is collected and the full characteristic energy peaks are observed in the spectrum. If the photon interacts in the epitaxial layer outside of the diodes, charge diffusion leads to charge being lost into neighbouring pixels. The amount of charge lost is dependent on the location of the initial photon and therefore there are many events which see a charge collection below the characteristic peaks. The gain of the sensors can be calculated using the  $k_{\alpha}$  peak, where all 1620 e<sup>-</sup> are collected by

$$Gain = \frac{Signal[mV]}{1620e^{-}} \quad , \tag{3}$$

where *Signal* is the mean value of a Gaussian fit to the  $k_{\alpha}$  peak.



Figure 11: The charge collection spectra for all sensors before and after irradiation and annealing where black is pre and red post exposure for sensors 2, 6 (unpowered), 9, and 12 (high resistivity).

Four sensors were tested before and after being irradiated and annealing had occured. To collect a sufficient number of events to resolved the  $k_{\alpha}$  peak a single Fe-55 scan took approximately 24 hours. For this reason the signal could only be studied after a long period of annealing to ensure that the results were not affected by annealing. Three of the sensors were powered during the exposure and the fourth was held at ground and received a much higher integrated dose. Prior to the sensors being exposed, the  $k_{\alpha}$  peak positions agreed within an acceptable spread of 10.8 mV. The  $k_{\alpha}$  peak in sensor 12 has an increased width due to the additional charge collection adjacent to the sensor diodes in the high resitivity silicon. Post exposure, the position of the  $k_{\alpha}$  peak increased in all of the sensors (see Figure 11) with a final spread of 9.4 mV.

#### 4.3 Signal to Noise

Table 2 gives a summary of the signal and gain for the test pixels obtained with the Fe-55 scans, and the noise of the bulk pixels from the threshold scans in DTU. Although the observed signal

August 24, 2012 – 12:01

DRAFT

and gain increased with radiation, the critical quantity is the signal to noise ratio (S/N). The fractional change was calculated using Equation 1 whilst S/N was given by:

$$\frac{S}{N} = \frac{Signal[mV]}{Noise[mV]} \quad , \tag{4}$$

where *Signal* is the position of the  $k_{\alpha}$  centroid and *Noise* is the noise taken from the threshold scans (in DTU) converted into mV by

$$Noise[mV] = Noise[DTU] \times C[DTU/e^{-}] \times Gain[mV/e^{-}] \quad , \tag{5}$$

where C is the conversion factor of DTU to electrons (3.3  $\text{DTU/e}^-$  [6]), and *Gain* is calculated using Equation 3. The values of the noise in electrons and mV are also given in Table 2.

Across all four sensors, S/N was observed to decrease after irradiation. When the sensor was powered during irradiation S/N decreased by between 4 % and 8 %. The results for the high resitivity sensor ( $6\pm1$  %) were consistent with the two standard sensors ( $4\pm1$  % and  $8\pm1$  %) demonstrating that the changes in S/N are independent of the epitaxial layer. The sensor irradiated at ground up to 5000 krad underwent a S/N decrease of  $15\pm1$  % showing that the sensor is capable of receiving large doses with a relatively small effect on S/N.

# 5 Conclusions

It has been shown that the noise in the TPAC sensors has increased by between 2.5 % and 8 % at 200 krad for various sensor bias rising to 21 % at 5000 krad for a sensor held at ground during exposure. The S/N has been shown to fall by a maximum of 8 % in sensors at a dose of 200 krad. At 5000 krad, the S/N has reduced by just 15 % which is very promising for future applications.

It has been demonstrated that changes in S/N are independent of epitaxial layer type as the sensors irradiated whilst powered were all in agreement. When the sensors are irradiated whilst powered, problems develop in the shift register leading to the need for a redesign of the shift register in future iterations of the sensors. The reduced dose rate gave rise to a vastly reduced number of configuration errors in the shift register. A dose rate of 6 rad/s yielded just three bad columns compared to greater than 20 bad columns for a dose rate of 60 rad/s. The dose rate received by the Silicon Inner Tracker, Silicon External Tracker, and the ECAL in CLIC ILD, and the ECAL in ILC ILD is orders of magnitude lower than 6 rad/s and as such the shift register issues would not present a problem even using the current TPAC technology.

### 6 Acknowledgements

We would like to thank Matt Wilson of Rutherford Appleton Laboratory and STFC for help and support during the course of sensor irradiations.

Cencor	Ser	nsor State	L [mV]	Gain [mV/a <sup>-</sup> ]	Noise [DTI ]]	Noice [a-]	Nuise [W	C/N
	Dose [krad]	Annealing [hours]						
y	0	ı	$194.6\pm0.1$	$0.120\pm0.0001$	$5.44\pm0.02$	$17.94\pm0.07$	$2.16\pm0.01$	$90.3\pm0.4$
D	5000	168	$202.2\pm0.2$	$0.125\pm0.0001$	$6.37\pm0.03$	$21.03\pm0.10$	$2.62\pm0.01$	$77.0\pm0.4$
ſ	0	ı	$191.8\pm0.1$	$0.118 \pm 0.0001$	$5.63\pm0.01$	$18.58\pm0.04$	$2.20\pm0.00$	$87.2\pm0.2$
1	220	282	$198.2\pm0.1$	$0.122\pm0.0001$	$5.88\pm0.04$	$19.42\pm0.13$	$2.38\pm0.02$	$83.4\pm0.5$
c	0	I	$202.6\pm0.1$	$0.125\pm0.0001$	$5.53\pm0.02$	$18.26\pm0.07$	$2.28\pm0.01$	$88.7\pm0.4$
n	200	250	$207.6\pm0.2$	$0.128 \pm 0.0001$	$6.02\pm0.03$	$19.87\pm0.11$	$2.55\pm0.01$	$81.5\pm0.5$
۲ د ا	0	I	$191.8\pm0.2$	$0.118 \pm 0.0001$	$5.50\pm0.03$	$18.16\pm0.11$	$2.15\pm0.01$	$89.2\pm0.5$
17	240	144	$201.5\pm0.1$	$0.124\pm0.0001$	$5.85\pm0.04$	$19.30\pm0.12$	$2.40\pm0.01$	$83.9\pm0.5$

Table 2: Summary of the noise and signal results from Section 4.1 and Section 4.2, and the S/N ratios calculated using Equation 4. Sensor 6 was unpowered and received a much larger integrated dose when compared to the other sensors. August 24, 2012 – 12:01

DRAFT

### References

- R. Turchetta. CMOS Sensors for the Detection of Minimum Ionising Particles. In Proceedings of the 2001 IEEE Workshop on Charge-Coupled Devices and Image Sensors, pp. 7–9. Lake Tahoe, Nevada, USA, 2001.
- [2] CALICE-UK Home Page. http://www.hep.ph.ic.ac.uk/calice/.
- [3] J. A. Ballin et al. Monolithic Active Pixel Sensors (MAPS) in a quadruple well technology for nearly 100% fill factor and full CMOS pixels. *Sensors 2008*, pp. 5336–5351, 2008.
- [4] A. Bevan, et al. Design Study for a SuperB Pixel Vertex Detector. 2010.
- [5] J. Ballin et al. Design and performance of a CMOS study sensor for a binary readout electromagnetic calorimeter. *JINST*, vol. 6 p. P05009, 2011.
- [6] P. Dauncey. Performance of CMOS sensors for a digital electromagnetic calorimeter. *PoS*, vol. ICHEP2010 p. 502, 2010.
- [7] The SPiDeR Collaboration, "DESY PRC Report", Oct 2009. http://www.hep.ph. imperial.ac.uk/calice/official/091105prc/spider.pdf.
- [8] A. A., et al. Updated niel calculations for estimating the damage induced by particles and gamma-rays in si and gaas. *Radiation Physics and Chemistry*, vol. 62(4) pp. 301–310, 2001.