Preliminary Results From Temperature Monitoring



31/03/2009

Monitoring setup

- Thermistors were attached to the following locations on and around sensor 07:
 - The non-substrate side of the sensor
 - The PCB
 - The frame holding the sensor in place
- Additionally the temperature of the substrate side of the sensor was monitored with a remote thermometer while the sensor was powered up (a temperature increase of ~9K was recorded).



Temperature Variations in Sensor 07

